



Date Saved: 12/3/2019 1:08:56 PM

Path: H:\WR\_PLANNING\Final\_Exhibits\WaterRightsApplication\Figure\_1-1.mxd




Date Saved: 11/25/2019 8:16:32 AM

Path: H:\WR\_PLANNING\Final\_Exhibits\WaterRightsApplication\Figure\_2-1.mxd




Path: H:\WR\_PLANNING\Final\_Exhibits\WaterRightsApplication\Figure\_2-2.mxd



Date Saved: 12/3/2019 11:06:20 AM

Path: H:\WR\_PLANNING\Final\_Exhibits\WaterRightsApplication\Figure\_2-3.mxd



Date Saved: 12/3/2019 10:34:01 AM

Path: H:\WR\_PLANNING\Final\_Exhibits\WaterRightsApplication\Figure\_2-4.mxd



**APPENDIX 3B** Photographs

## **Appendix 3B-1 – Diversion Reach Photographs**

Figure 1 – Field Reconnaissance Photos

Photo 1. Typical conditions of the downstream end of the proposed river reach (Diversion Point B) facing downstream (approximately south).

Photo 2. Typical conditions of the downstream end of the proposed river reach (Diversion Point B) facing upstream (approximately north).

Photo 3. Typical conditions of the downstream end of the proposed river reach (Diversion Point B) facing left bank (approximately east).


Photo 4. Typical conditions of the downstream end of the proposed river reach (Diversion Point B) facing right bank (approximately west).

Photo 5. Typical conditions of the upstream end of the proposed river reach (Diversion Point A) facing downstream (approximately east).

Photo 6. Typical conditions of the upstream end of the proposed river reach (Diversion Point A) facing upstream (approximately west).

Photo 7. Typical conditions of the upstream end of the proposed river reach (Diversion Point A) facing left bank (approximately north).


Photo 8. Typical conditions of the upstream end of the proposed river reach (Diversion Point A) facing right bank (approximately south).



Path: H:\WR\_PLANNING\Final\_Exhibits\WaterRightsApplication\Figure\_A-x1.mxd




**Photo 1.** Typical conditions of the downstream end of the proposed river reach (Diversion Point B) facing downstream (approximately south).




**Photo 2.** Typical conditions of the downstream end of the proposed river reach (Diversion Point B) facing upstream (approximately north).




**Photo 3.** Typical conditions of the downstream end of the proposed river reach (Diversion Point B) facing left bank (approximately east).



**Photo 4.** Typical conditions of the downstream end of the proposed river reach (Diversion Point B) facing right bank (approximately west).




**Photo 5.** Typical conditions of the upstream end of the proposed river reach (Diversion Point A) facing downstream (approximately east).



**Photo 6.** Typical conditions of the upstream end of the proposed river reach (Diversion Point A) facing upstream (approximately west).



**Photo 7.** Typical conditions of the upstream end of the proposed river reach (Diversion Point A) facing left bank (approximately north).




**Photo 8.** Typical conditions of the upstream end of the proposed river reach (Diversion Point A) facing right bank (approximately south).

## Appendix 3B-2 – Off-Channel Reservoir (OCR) Site Photographs

Figure 2 Environmental Memorandum Photos
Photo 1: Typical row crop field (facing north) within proposed project area
Photo 2: Typical pasture (facing north) within proposed project area
Photo 3: Stream 1, Keller Creek, facing downstream
Photo 4: WET2 facing north.
Photo 5: Ditch 1 facing upstream.
Photo 6: Ditch 7 facing downstream.
Photo 7: Ditch 11 facing downstream.
Photo 8: Ditch 17 facing upstream.
Photo 9: Pond 1 facing north.
Photo 10: Pond 2 facing east.
Photo 11: Wet 3 facing north. A good representation of a sedge meadow (*Cyperus spp.*).
Photo 13: Wet 17 facing east. A good representation of upland species encroachment.

Photo 14: Wet 21 facing east. A good representation of a linear wetland.



Date Saved: 11/25/2019 8:10:13 AM

Path: H:\WR\_PLANNING\Final\_Exhibits\WaterRightsApplication\Figure\_A-x2.mxd



Photo 1: Typical row crop field (facing north) within proposed project area



Photo 2: Typical pasture (facing north) within proposed project area



Photo 3: Stream 1, Keller Creek, facing downstream



Photo 4: WET2 facing north.



Photo 5: Ditch 1 facing upstream.



Photo 6: Ditch 7 facing downstream.



Photo 7: Ditch 11 facing downstream.



Photo 8: Ditch 17 facing upstream.



Photo 9: Pond 1 facing north.



Photo 10: Pond 2 facing east.



Photo 11: Wet 3 facing north.



Photo 12: Wet 5 facing north. A good representation of a sedge meadow (*Cyperus spp.*).



Photo 13: Wet 17 facing east. A good representation of upland species encroachment.



Photo 14: Wet 21 facing east. A good representation of a linear wetland.